	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
1	BRS	L1	1	"6749365".pn.	USPAT	2004/11/22 19:22			
2	BRS	L2	26	((vibratory vibration vibrating) with screed$) and handle and frame and (motor engine) and (elastomeric isolat$)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	2004/11/22 19:29			
3	BRS	L3	142	((vibratory vibration vibrating) with screed$) and (rubber shock elastomeric absorbing absorber) and "404"/$.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	2004/11/22 19:34			
4	IS&R	L4	5	(("4,591,291") or ("5,460,461") or ("5,980,154") or ("5,540,519") or ("6,231,331")).PN.	USPAT	2004/11/22 19:34			

Type	L #	Hits	Search Text	DBs	Time Stamp	Comment s	Error Definition	Err ors
BRS	L5	58	("0919993" | "1955101" | "2180198" | "2255343" | "2303335" | "2314985" | "2372163" | "2386662" | "2400321" | "2651980" . | "2746367" | "2999261" | "3427939" | "3883259" | "3917426" | "4043694" | "4349295" | "4359296" | "4375351" | "4386901" | "4388018" | "4408978" | "4427358" | "4591291" | "4641995" | "4650366" | "4685826" | "4758114" | "4798494" | "4838730" | "4848961" | "4861188" | "4911575" | "5096330" | "5244305").PN. OR ("5375942").URPN.	US-PGPUB; USPAT; USOCR	2004/11/22 20:23			

5

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
6	BRS	L6	26	("3067656" | "3180625" | "3427939" | "4431336" | "4466757" | "4591291" | "4641995" | "4702641" | "4798494" | "4892437" | "5147146" | "5244305" | "5375942" | "5829874" | "5857803" | "5984571" | "6053259" | "6089787" | "6231331" | "6296467" | "6322286" | "6374569" | "6467560").PN. OR ("6705799").URPN.	US-PGPUB; USPAT; USOCR	2004/11/22 20:23			